

CNC PART PROGRAMMING AND COST ANALYSIS ON VERTICAL MACHINING CENTRE (VTC)

Dr. V.S.S. Murthy¹ P. Sreenivas²

¹Professor and Principal of K.S.R.M College of Engg, Dept of Mechanical Engineering, Kadapa, Andhra Pradesh, India)

²(Assistant Professor, Dept of Mechanical Engineering, K.S.R.M College of Engg, Kadapa, Andhra Pradesh, India)

ABSTRACT: In the present study in view of the latest development and revolutionary changes taking place in CNC field through the world, Mechanical elements have to be designed and manufactured to precision, which is perfectly and easily possible through these modern CNC machines. This work is based on the capacity and capability of vertical machining Centre (VTC) with auto tool changer. The top slide which was part programmed can be machined using VTC. And Machining Time is compared in between carbide and hardened tools. The "Top slide" of lathe's called for powerful NC programming technique were used absolute position type data input system using G codes, M codes, polar coordinate programs, circular and linear interpolation, canned cycles etc. The above mentioned component – top slide being manufactured by using various Conventional machine tools like horizontal milling, vertical milling, surface grinding, boring machine and slotting machines. This involved a considerable lead time and usually delayed the assembly schedule. it has been modified and adopted for regular production on this machine, in two setups there by boosting their productivity and ensuring quality in each and every piece. Finally, we can establish for regular production.

KEYWORDS: CNC Programming, Machining Time, carbide & hardened Tools.

I. INTRODUCTION

I.1. NUMERICAL CONTROL: Numerical control (NC) can be defined as a form of programmable automation in which the process is controlled by numbers, letters and symbols. In NC, the numbers form a program of instructions of designed for a particular work part or job.

The definition of NC given by electronic industries association (EIA) is "A system in which actions are controlled by direct insertion of numerical data at some point. The system must automatically interpret at least some portion of this data."

A Numerical control (NC) system is used when

- The number of components per component is large
- Size of batches is medium
- Labour cost for the component is high
- The component requires special tooling
- Ratio of cutting time to non-cutting time is high
- Design changes are frequent

I.2. BASIC ELEMENTS OF A NC SYSTEM:

An operational numerical control system consists of three basic components

- Controller unit also known as machine control unit (MCU)
- Machine tool or other machining centre
- The program of instructions serves as the input to the controller unit, which in turn commands the machine tool or other process to be controlled.

I.2.1 PROGRAM OF INSTRUCTIONS: The program of instructions is the detailed step-by-step set of directions which instructs the machine tool what to do. It is coded in numerical or symbolic form on some type of input medium that can be interpreted by the controller unit. The input media used can be punched cards/ magnetic disk or tape/punched tape. There are two methods of inputs in the NC system.

- By manual entry of instructional data to the controller unit and this method is called manual data input (MDI) and is appropriate only for relatively simple jobs where the order will not be protected.
- By means of a direct link with a computer. This is called direct numerical control (DNC).




Fig.1 Basic Components of NC system

- Part programmer prepares the program of instructions. The programmer's job is to provide a set of detailed instructions by which the sequences of processing steps are to be performed.
- The processing steps for a machining operation are the relative movement between the cutting tool and the work piece

I.2.2 CONTROLLER UNIT: The controller unit consists of the electronics and hardware that reveals and interprets the program of instructions and converts it into mechanical actions of the machine tool. The controller unit elements are tape

reader, a data buffer, signal output to the machine tool Feedback, channel from the machine tool and data decoding control area.




Fig 2. Machine controller unit

I.3. NUMERICAL CONTROL (NC) PROCEDURE:

The basic steps in NC procedure to utilize NC in manufacturing are

- Process planning
- Part programming
- Part program entry/ tape preparation
- Proving the part programs/ tape verification
- Production

I.3.1. PROCESS PLANNING: Process planning is the procedure of deciding what operations to be carried on the component, in what order and with what tooling and work holding facility. Both process planning and part programming for manufacturing occur after the detail drawing a component has been prepared.

I.3.2. PART PROGRAMMING: In part programming, sequence of steps to be performed by NC planned and documented. There are two methods by which a part program is accomplished manual part programming and computer assisted part programming.

In manual part programming the relative cutter/work piece positions which must be following to machine the part are listed in a format known as part program manuscript. For complex work piece geometries and jobs with many machining steps, computer-assisted part programming is used.

I.4 TOOLINGS FOR CNC (VERTICAL MACHINING CENTRE): The modern machine tools are designed to operate at higher speeds and feeds. They possess improved accuracy, higher rigidity and reduced noise levels. The cost of raw material input is very high-of the order of 40% for general purpose machine tools. This calls for optimizing the design of machine elements, selecting the right type of materials, judiciously imparting effective fabrication and treatment method.

I.5 GENERAL PRINCIPLES IN THE SELECTION OF MATERIALS FOR MACHINE TOOLS:

I.5.1 FUNCTIONAL REQUIREMENTS: The functional requirements must be met in terms of various properties. For example, in the selecting material for the main spindle of a machine tool, the modulus of elasticity and the surface hardness required for the spindle nose, bore and the locations of the bearings are important properties which need to be considered. Generally, low nickel-chromium alloy case carburized steel such as 15CrNi6 (as per DIN 17210) is selected, which meets the functional requirements.

I.5.2 EASE OF FABRICATION: The process of fabrication should be such that the part or component should be easy to make. If it is required in batch quantity, casting process is adopted. For example, machine tool elements or parts such as bed, headstock, etc. required in batch quantity are made out of casting process in the foundry. If the requirement is one or two numbers, a welding process is used to fabricate the part.

I.5.3 MACHINABILITY: This is another important parameter to be considered for selecting the raw material of machine tool components as extensive machining is involved. Construction steels such as medium carbon steel (C45 as per DIN 17200) and low alloy steel (15CrNi6 as per DIN 17210, 36CrNiMo4 as per DIN 17200 and 34CrAlMo5 as per DIN 17211) are chosen for many of the parts which have good machinability. In case of castings, grey cast iron is selected.

I.5.4. COST: Since the raw material cost plays a significant role in the overall cost of the machine tool, it becomes an important factor to be considered.

I.5.5. AVAILABILITY: The chosen material must be easily available so that the cost and delivery time are kept low. In fact, all the raw materials required for machine tools are easily available in India.

I.5.6. MATERIALS FOR CUTTING TOOLS: One of the main qualities that a cutting tool must possess is that it retains its hardness at high temperatures generated during the cutting process. The most common cutting tool materials used in CNC application or HSS sintered carbides.

II. CANNED CYCLES

A canned cycle (fixed cycle) defines a series of machining sequences for drilling, boring, tapping.

The canned cycles G81 to G89 are stored as subroutines L81 to L89.

The user may deviate from a standard fixed cycle and redefine it to suit his specific machine or tooling requirements. The parameters R00 to R11 are used by subroutines to define the variable values necessary to correctly execute a fixed cycle prior to a subroutine call; all necessary parameters must be defined in the main program.

A fixed cycle call is initiated with G80 to G89. G81 to G89 are fixed cycles that are cancelled with G80. A boring cycle can be called with L81 to L89, however, L81 to L89 are not model. L81-L89 is performed only once in the block in

which it is (notable tungsten carbides), ceramic and polycrystalline diamond. High speed steel is tougher than cemented carbide but not so hard and therefore, cannot be used at such high rate of metal removal, not suitable from higher cutting speeds.

The hardness of the cemented carbide is almost equal to that of diamond. It deserves this hardness from its main constituent, tungsten carbide. In its pure form tungsten carbide is too brittle to be used as a cutting tool. So it is pulverized and mixed with cobalt. The mixture of tungsten carbide and cobalt powder is pressed into the required shape and then sintered. The cobalt metal binds the tungsten carbide grains in to a dense, non-porous structure.

In addition to tungsten carbide, the other metals as titanium and titanium carbides (TIC) are used and by providing tungsten carbide tool with a thin layer of titanium carbide tool, resistance of to wear and useful life are increased up to 5 times. Programmed. At the end of a fixed cycle the tool is re-positioned at the starting point.

II.1 USING CANNED CYCLES IN PROGRAMS

CALL-UP G81 (DRILLING, BORING, CENTERING, BORING AXIS Z)

N8101 G90 S48 F460 LF - Spindle ON
 N8102 G00 D01 Z500 LF - Active tool offset
 N8103 X100 Y150 LF - First drill position
 N8104 G81 R02 360 R03 250 R11 3 LF - Call cycle
 N8105 X250 Y300 LF - Second drill position and automatic G81 call
 N8110 G80 Z500 LF - Cancelling G81 and returning to Starting plane

CALL-UP WITH L81:

N8101 G90 S48 F460 LF
 N8102 G00 D01 Z500 LF
 N8103 X100 Y150 LF
 N8104 L81 R02 360 R03 250 R11 3 LF – Call up drilling cycle first hole
 N8105 X250 Y300 LF
 N8106 L81 R02. . . LF – Call- up drilling cycle, second hole
 N8107 Z500 LF

As opposed to the call-up with G81, here the drilling cycle must be called up a new at every new drill position

CALL – UP G82 (DRILLING, COUNTER, SINKING)

N8201 ... M03 F460 LF
 N8202 G00 D01 Z500 LF
 N8203 X100 Y150 LF
 N8204 G82 R02 360 R03 250 R04 1 R11 3 LF
 N8205 X250 Y300 LF
 N8206 G80 Z500 LF




Fig 3

CALL – UP G83 (DEEP HOLE DRILLING)

First drilling depth 50 mm R01 50
 Reference plane = retract plane 146 mm R02 146
 Final drilling depth 5 mm R03 5
 Dwell at starting point 5 s R00 5
 Dwell at final depth 1 s R04 1
 Degression value 20 mm R05 20
 Drilling axis (z) 3 R11 3
 N8301 ... S48 M03 F460 LF
 N8302 G00 D01 Z500 LF
 N8303 X100 Y150 LF
 N8304 G83 R01 50 R02 146 R03 5 R00 5
 R04 1 R05 20 R11 3 LF
 N8305 X250 Y300 LF
 N8306 G80 Z500 LF

At the rapid traverse advance with respect to the new drilling depth, a safety distance of 1mm is kept (on account of the chips still remaining in the hole). With the inch system (G70) the safety distance must be changed accordingly.




Fig 4

CALL – UP G84 (tapping cycle):-

```

N8401 ... S48 M03 F460           LF
N8402 G00 D01 Z500              LF
N8403 X100 Y150                 LF
N8404 G84 R02 360 R03 340 R06 04
R07 03 R11 3                    LF
N8405 X250 Y300                LF
N8406 G80 Z500                 LF
    
```




Fig 5

CALL – UP G85 (BORING 1) :

```

N8501 ... S48 M03 F460           LF
N8502 D00 D01 Z500              LF
N8503 X100 Y150                 LF
N8504 G85 R02 360 R03 250 R10 380 R11 3
N8505 X250 Y300                LF
N8506 G80 Z500                 LF
    
```

CALL – UP G86 (BORING 2):-

```

N8601 ... S48 M03 F460           LF
N8602 G00 D01 Z500              LF
N8603 X100 Y150                 LF
N8604 G86 R02 360 R03 250 R07 03
R10 380 R11 3                    LF
N8605 X250 Y300                LF
N606 G80 Z500                 LF
    
```

CALL – UP G87 (BORING 3):

```

N8701 ... S48 M03 F460           LF
N8702 G00 D01 Z500              LF
N8703 X100 Y150                 LF
N8704 G87 R02 360 R03 250 R07 03 R11 3
N8705 X250 YY300                LF
N8706 G80 Z500                 LF
    
```





Fig 6




Fig 7

CALL – UP G88 (BORING 4):

```

N8801 ..... S48 M03 F460 LF
N8802 G00 D01 Z500 LF
N8803 X100 Y150 LF
N8804 G88 R02 360 R03 250 R04 1 LF
          R07 03 R11 3
N8805 X250 Y300 LF
N8806 G80 Z500 LF
    
```

CALL-UP G89 (BORING 5):-

```

N8901 ..... S48 M03 F460 LF
N8902 G00 D01 Z500 LF
N8903 X100 Y150 LF
N8904 G89 R02 360 R03 250 R04 1 LF
          R1103
N8905 X250 Y300 LF
N8906 G80 Z500 LF
    
```





Fig 8

II.2 CALLING BORING CYCLES IN A SUBROUTINES:

If boring cycles are called in a subroutine, the following procedure is necessary:

```

%1R02 360 R03 250 R00 81 R11 3 LF- supply boring cycle parameters
L0101 LF-boring positions
M30* LF
L0101 (Boring positions)
GR00 X1 Y1 LF-First boring location
X2 Y2 LF-Second boring location
X5 Y5 LF-Third boring location
X10 LF-Fourth boring location
G80 M17 LF-Deselect boring cycle and end of subroutine
R02 360 R03 250 R00 81 R11 3 LF- supply boring cycle parameters
L0101 LF-boring positions
M30* LF
L0101 (Boring positions)
GR00 X1 Y1 LF-First boring location
X2 Y2 LF-Second boring location
X5 Y5 LF-Third boring location
X10 LF-Fourth boring location
G80 M17 LF-Deselect boring cycle and end of subroutine
    
```

II.3 POLAR COORDINATES G10/G11/G12/G13: Drawing dimensioned with an angle and radius can be entered directly in the program with the aid of the polar coordinates.

The following preparatory functions are available for Programming with coordinates:-

- G10 Linear interpolation, rapid traverse
- G11 Linear interpolation, federate (F)
- G12 Circular interpolation, clockwise

G13 Circular interpolation, counter clockwise.

The action of the preparatory functions is:-
MODEL:




Fig 9

W - Work piece zero

M - Centre point of polar coordinate system

A - Angle

U - Radius

In order to determine the traverse path, the control requires the centre point, the radius and the angle. The centre point is entered with perpendicular coordinates (X,Y,Z) and on initial programming using absolute position data. A subsequent incremental position data input (with G91) always refers to the last centre point programmed.

2.3.1. Polar coordinates g110/g111: The functions G110 and G111 are used to adopt a new centre point or zero point when programming polar coordinates.

Using the new centre point, the angles are again taken from the horizontal and the radius is calculated from the new centre point. G110 and G111 have the following meanings.

G110 Adopt the set point reached as the new centre point

G111 Centre point programming with angle and radius without axis movement

(Example: setting the arc centre of a hole circle)

The following traversing movement must be programmed using G110

Ex: polar coordinates G110

Z385

(G110 polar coordinates) Lf

N05 G90 G10 X0 Y0 U0 F1000 Lf

N10 G11 U30 A45 Lf

N15 G11 U20 A30 Lf

N20 M30 Lf




Fig 10

Feed rate F, G94/G95/G98

The federate F is programmed in mm/min or mm/rev

G94 F federate in mm/min

G95 F federate in mm/rev (is assigned to the leading spindle)

G98 F federate in rev/min (for rotary axes only)

II.3.2.Thread cutting G33/G34/G35: Threads can be cut both on drilling or boring and milling machines with a boring tool or a facing tool. These are various types of thread which can be cut as follows:

- i. Threads with a constant lead
- ii. Threads with a variable lead
- iii. Single or multiple threads
- iv. External or internal threads

The following preparatory functions are available for machining threads;


G33 threads cutting with constant lead

G34 thread cutting with linear lead increases

G35 thread cutting linear lead decreases



Fig 11.TOP SLIDE SECTIONAL VIEWS SET UP -1



SCALE 1:3

FIG 12. Cross section of top slide for setup-1




Fig 13. Cross section of top slide for setup-II

TOOL	DIAMETER
BW drill	60
Boring bar	64.5
BW drill	38
Boring bar	21.8
Inserted type end mill	25
Three lip end mill	12
Boring bar(Finishing)	65
Boring bar(finishing)	22
Shoulder milling cutter	63

III.1. MACHINE SPECIFICATIONS

VMC 1200
 SOFTWARE SIEMENS
 AXIS MOVEMENT 3
 TOOLPOST CARRYING CAPACITY 24
 X-AXIS 1200 MM
 Y-AXIS 600 MM
 Z-AXIS 600 MM
 GUIDEWAYS T-SLOT BED
 SPEED MAXIMUM 600 R.P.M
 SPEED MINIMUM 50 R.P.M
 FEED RATE 10 TO 250
 MM/MIN

N55 M0
 N60 L90: [DIA64.5 SIF B. BAR]
 N65 T2
 N70 M06
 N75 G54 S300 F30 D1
 N80 G0 X0 Y0
 N95 CYCLE 86 [DIA 38 BW DRL]
 N105 MCALL
 N110 M0
 N115 N90; [DIA38 BW DRL]
 N120 T3
 N125 M06
 N130 G54 S350 M03 F35 D1
 N135 G0 X453.5 Y18.5
 N150 CYCLE82 (150, 0, 2, -28, , 1)
 N160 MCALL
 N170 L90; [DIA 41.5 SIF B.BAR]
 N175 T4
 N180 M06
 N185 G54 S400 M03 F30 D1
 N190 G0 X453.5 Y1895
 N205 CYCLE 86 (200, 0, 2, -28, , 2, 3, , ,)
 N205 MCALL

III.2. PART PROGRAM:

III.2.1 SETUP – I:

N5 L90; [DIA60 CORE DRILL]
 N10 T1
 N15 M06
 N20 G54 S200 M3 F30 D1
 N25 G0 X0 Y0
 N40 CYCLE 82 (150, 0, 2, -90, 1)
 N50 MCALL

```

N215 M0
N220 M0
N225 L90; .... [DIA 63 S/MILL]
N230 T5
N235 M06
N240 G54 S350 M03 F150 D1
N245 G0 X0 Y0
N250 R20 = 27 R21 = 3 R22 = 14.7
N255 MS1: G0 Z = -R20
N260 G01 X-50
N265 G02 X-50 Y0 I50 J0
N270 G01 X-67.5
N275 G02 X-67.5 Y0 I67.5 J0
N280 G01 X0 Y0
N285 IF R20 == R22 GOTOF MS2
N290 R20 = R20+R21
N295 GOTOB MS1
N300 MS2 GO Z200
N305 M0
N310 L90; ....[DIA25 END MILL]
N315 T6
N320 M06
N325 G54 S800 M03 F100 D1
N330 TRANS X348 Y0
N335 GO X-25 Y0
N340 Z-3.5
N345 G01 X-52.5
N350 Y67.5
N355 X52.5
N360 Y-67.5
N365 X-52.5
N370 Y0
N375 X-25
N380 TRANS X0 Y0
N385 G0 Z200
N390 M0
N395 L90; ....[DIA12 END MILL]
N400 T7
N405 M06
N410 G54 S1000 M03 F100 D1
N415 GO X-40 Y0
N425 Z-3.5
N430 G01 X-59
N435 Y74
N440 X59
N445 Y-74
N450 X-59
N455 Y0
N460 X-40
N465 TRANS X0 Y0
N470 G0 Z200
N475 M0
N480 L90; .....[SPOT]
N485 T8
N490 M06
N495 G54 S1000 M03 F100 D1
N500 G0 X509 Y-19
N515 MCALL CYCLE 82 (10, 0, 2, - 3.5, , 1)
N525 X509 Y-19
N530 Y31
N535 X242 Y0
N540 X192 Y31
N545 MCALL
N550 G0 Z200
N555 M0
N560 L90; .....[DIA200 SIF BORE]
N565 T9
N570 M06
N575 G54 S100 M03 F10 D1
N580 G0 X0 Y0
N595 CCYCLE86 (200, 0, 2, -15, , 2, 3, , , ,)
N605 MCALL
N610 M0
N615 L90; ..... [DIA 42 H7]
N620 T10
N625 M06
N630 G54 S400 M03 F30 D1
N635 G0 X0 Y0
N650 CYCLE86 (150, -12, 2, -85, , 2, 3, , ,)
N660 MCALL
N665 M0
N670 L90; ..... [DIA 42H7]
N675 T11
N680 M06
N685 G54 S600 M03 F30 D1
N690 G0 X453.5 Y18.95
N705 CYCLE86 (150, 0, 2, -28, , 2, 3, , ,)
N715 MCALL
N720 M0
N725 L90; .... [DIA 100 SIM]
N730 T12
N735 M06
N740 G54 S300 M03 F200 D1
N745 G0 X-175 Y70
N750 Z0
N755 G01 X610
N760 G0 Y0
N765 G01 X-175
N770 G0 Y-70
N775 G01 X610
N780 G0 Z200
N785 M30
== eof ==

III.2.2.SETUP - II
N5 L90; ....[DIA 63 S/M]
T5
M06
N10 G54 S400 M03 F200 D1
G0 X-55 Y202
Z-1
G01 X570
Y28
X-10
Y-40
N15 G0 X700 Y130
Z0
G01 X560
G0 Z250
M0
N16 L90; .....[SPOT]
T8
M06
N20 G54 S1000 M03 F50 D1
G0 X100 Y17

```


MCALL CYCLE 82 (10, 0, 2, -3.5, , 0)
 X100 Y17
 X402
 Y213
 X100
 MCALL
 G0 Z200
 M0
 N30 L90;[OIL GROVING]
 T14
 M06
 N40 G54 S1000 M03 F100 D1
 G111 X100 Y17
 RP = 17.5 AP = 225 F = 100
 G0 Z0
 G01 Z-17
 G111 X100 Y17
 AP = 45 RP = 29
 G0 Z2
 G111 X402 Y17
 RP = 17.55 AP = 315
 G01 Z-1.7
 G111 X402 Y17
 RP = 29 AP = 13.5
 G0 Z2
 G111 X402 Y213
 RP = 17.5 AP = 45
 G01 Z-1.7
 G111 X402 Y213
 AP = 225 RP = 22.5
 G0 Z2
 G111 X100 Y213
 RP = 17.5 AP = 135
 G01 Z-1.7
 G111 X100 Y213
 AP = 315 RP = 29
 G0 Z300
 M0
 N50 L90;[DIA 63 S/MILL]
 T5
 M06
 N60 S400 M03 F200 D1
 G0 X-35 Y155.22
 R20 = 4.4 R21 = 3 R22 = 25.4
 MS1: G0 Z = -R20
 G01 X0
 X558 Y162.52
 X563
 G0 Y100
 G01 Y74
 X-35
 G0 Y155.22
 IF R 20 == R22 GOTOF MS2
 R20 = R20 + R21
 GOTOB MS1
 MS2: GO Z100
 N70 GO X-40 Y115
 Z-20
 G01 X260
 GO Z-25.4
 G01 X-45
 G0 Z-25
 N70 TRANS X110 Y115

G0 X0 Y0
 R20 == 29.4 R21 = 4 R22 = 41.4
 PR1: G0 Z = -R20
 G01 X17.5
 G02 X17.5 Y0 I-17.5 J0
 G01 X0 Y0
 IF R20 == R22 GOTOF PR2
 R20 == R20 + R21
 GOTOB PR1
 PR2: TRANS X0 Y0
 G0 Z200
 M0
 N70 L90;[50 DOVETAIL]
 T15
 M06
 N80 G54 S80 M03 F50 D1
 R20 = 74 R21 = 2 R22 = 66
 XY: X-45 Y = R20
 Z-25.5
 G01 X562
 Y90
 G0 X550
 Z80
 IF R20 == R22 GOTOF XY2
 R20 = R20-R21
 GOTOB XY1
 XY2: M0
 N90 X65.5
 Z-25.5
 G01 X562
 Y90
 G0 X550
 Z80
 N100 R20 = 5 R21 = 2 R22 = 63
 X21: TRANS Y = R20
 G0 X-45 Y144.72
 Z-25.5
 G01 X0
 X558 Y152.005
 X562
 TRANS Y0
 Y150
 G0 X550
 Z80
 IF R20 == R22 GOTOF XZ2
 R20 = R20+R21
 GOTOB XZ1
 MZ 2: M0
 N110 TRANS X0 Y0
 G0 X-55 Y115
 Z-25.5
 G01 X260
 G0 Z300
 M30
 N90 L90; ...[DIA 100 S/F]
 T16
 M06
 N90 G54 S200 M03 F30 D1
 G0 X110 Y115
 CYCLE 86 (150, -24, 2, -41.5, , 2, 3, , , , ,)
 MCALL
 M0
 N100 L90

T17
M06
N110 S600 M03 F150 D1
G0 X574 Y-20
R20 = 8 R21 = 8 R22 = 32
JK 1: G0 Z= -R20
G01 Y70
N800 G01 Y701
N805 G0 Z10
N810 Y-20
N815 IF R20 == R22 GOTOF JK2
N820 R20 = R20 + R21
N825 GOTOB JK1
N830 JK2: G0 Z10
N835 G0 X574 Y12
N840 Z32
N845 G01 X674
N850 G0 Y40
N855 G01 X574
N860 G0 Z300
N865 Y400

N870 M0
N875 G0 X574 Y250
N880 R20 = 8 R21 = 8 R22 = 32
N885 JH1: Z = -R20
N890 G01 Y175
N895 G0 Z10
N900 Y250
N905 IF R20 == R22 GOTOF JH2
N910 R20 = R20 + R21
N915 GOTOB JH1
N920 JH2: G0 Z10
N925 G0 X574 Y250
N930 Z-32
N935 G01 Y218
N940 X674
N945 G0 Y188
N950 G01 X580
N955 G0 X200
N960 M30
= =eof = =

IV. MACHINIG TIME

IV.1 INTRODUCTION

Machining process converts raw material into useful finished product, surface finishing is needed to the foundry castings certain amount of material is added as a machining allowance for this purpose the size of the casting should be slightly over size than the dimensions shown on the finished drawings the machining operations generally performed on vertical machining center are:

- Drilling
- Boring
- Shaping
- Grinding
- Reaming
- Milling etc.

IV.2 PURPOSE OF ESTIMATING MACHINING TIME:

Estimation of machining time for different processes is required for the following processes:

- To estimate the manufacturing time
- To fix the delivery dates
- To determine the cost of labour charges
- To find out the cost of manufacturing different parts

IV.3 MACHINING TIME

Estimation of machining time means calculation of time required to finish the given component according to the drawings supplied after giving number of allowances in addition to the actual time taken for machining operations certain amount of extra time is given to the workers. They are:

- Setup time
- Handling inspection of jobs
- Team down time
- Fatigue allowance
- Tool changing allowance
- Measurement checking allowance
- Other allowances for cleaning
- Getting stock etc.

There for total machining time is the actual time for machining and all the time allowances as given above.

To calculate actual machining time the basic general formula used is

$$\text{Machining time} = \text{length of cut} / (\text{feed} \times \text{rpm})$$

IV.4 CUTTING SPEED:

The cutting speed of a cutting tool may be defined as the speed at which the cutting edge passes over the material. Cutting speed is generally expressed in m/min.

An estimator should consider the following while selecting a suitable cutting speed.

Low cutting speeds are required for hand materials.

- High speed steel cutting tools content high speeds and can bide tipped tools cut still higher speeds.
- If the depth of cut and feed is more/less cutting speed may be taken and vice-versa

- Cutting speeds can be increased by using good cutting fluids and coolants.
- The amount of stock removed is inversely proportional to the cutting speeds when stock is removed at high speeds.
- If the cutting speed increases the heat generated also increases and tool life decreases.

Cutting speed is given by the formula:

$$S = (\pi DN) / 1000 \text{ meters/min}$$

IV.5. MACHINING TIME FOR CARBIDE TOOLS:

4.5.1. SETUP – I:

For DIA60mm core drill,

$$\text{Cutting speed (s)} = \pi DN/1000 = (1000 \times 45)/(\pi \times 60) = 200 \text{ rpm}$$

$$\text{Feed rate (F)} = \text{feed/tooth} \times \text{no. of teeth} \times \text{Rpm} = 0.1 \times 2 \times 200 \quad F = 30 \text{ mm/min}$$

$$\text{M/C time (or) operating time} = \text{length/feed} = 92/30$$

$$\text{Time} = 4 \text{ min}$$

For DIA 64.5 S/F B. BAR

$$\text{Operating time} = \text{length/feed} = 92/30 \quad T = 4 \text{ min}$$

For DIA 38 between DRL

$$C/s = \pi dn/1000$$

$$N = (45 \times 1000) / (\pi \times 38) \quad N = 350 \text{ rpm (spindle speed)}$$

$$\text{Feed} = 0.1 \times 1 \times 350 = 35 \text{ mm/min}$$

$$\text{Operating time} = 30/35 \text{ (length/feed)} \quad T = 1 \text{ min}$$

For DIA 41.5 S/F B. BAR

$$C/s = \pi dn/1000$$

$$N = (1000 \times 45) / (\pi \times 41.5) = 300 \text{ rpm}$$

$$F = 0.1 \times 1 \times 300 = 30 \text{ mm/min}$$

$$\text{Operating time} = \text{length} / \text{feed} = 30/30 = 1 \text{ min}$$

For DIA 63 S/MILL S/s = 350 rpm [R = 67.5min]

$$\text{Feed} = 150 \text{ mm/min} \quad [\text{no. of passes} = 5]$$

$$\text{Operating time} = 2\pi R \times \text{no. of passes} / \text{feed} = 2\pi \times 67.5 \times 5 / 150 = 15 \text{ min}$$

For DIA 25 END MILL s/s = 800 rpm

$$\text{Feed} = 100 \text{ mm/min}$$

$$\text{Operating time} = \text{length/feed} = 480/100 \quad T = 5 \text{ min}$$

For DIA 12 END MILL S/s = 1000 rpm

$$\text{Feed} = 100 \text{ mm/min}$$

$$\text{Operating time} = \text{length} / \text{feed} = 532 / 100 \quad T = 6 \text{ min}$$

For DIA 200 S/F BORE s/s = 100 rpm

$$\text{Feed} = 10 \text{ mm/min}$$

$$\text{Operating time} = \text{length} / \text{feed} = 17 / 10 = 2 \text{ min}$$

For DIA 42 H₇ S/S = 400 rpm

$$\text{Feed} = 30 \text{ mm/min}$$

$$\text{Operating time} = \text{length} / \text{feed} = (87+30)/30 \quad T = 4 \text{ min}$$

For DIA 100 S/M S/s = 300 rpm

$$\text{Feed} = 200 \text{ mm/min}$$

$$\text{Operating time} = \text{length/feed} = 1850/200 \quad T = 10 \text{ min}$$

TOTAL OPERATING TIME FOR SETUP – I

$$= 4+4+1+1+15+15+6+2+4+10 \quad T = 52 \text{ min}$$

8.5.2.SETUP-II

For DIA 63 S/M S/s = 400 rpm

$$\text{Feed} = 200 \text{ mm/min}$$

$$\text{Operating time} = \text{length} / \text{feed} = 1218 / 200 \quad T = 7 \text{ min}$$

For spot

$$T = 5.5/50 = 1 \text{ min}$$

For oil grooving

$$\text{Feed} = 100 \text{ mm/min}$$

$$\text{Time} = \text{length} / \text{feed} = [(29 + 17.5)/100] \times 4 = 2 \text{ min}$$

For 63 s/m

$$F = 200 \text{ mm/min}$$

$$\text{Operating time} = \text{length/feed} = (\text{length} \times \text{no. of passes}) / \text{feed}$$

$$= [(558 \times 2 + 162 \times 2)/200] \times 8 \quad T = 58 \text{ min}$$

$$\text{Total length} = 2\pi R \times \text{no. of passes} = 2\pi \times 17.5 \times 4$$

$$\text{Time} = (2\pi \times 17.5 \times 4)/200 = 3 \text{ min}$$

For 50 DOVETAIL S/s = 80 rpm

$$\text{Feed} = 50 \text{ mm/min}$$

$$\text{Operating time} = (\text{total length} \times \text{no. of passes})/\text{feed} = [(607+90-74) \times 5]/50 \quad T = 62 \text{ min}$$

$$\text{Operating time} = [603 + (152.005 - 144.72) \times 4]/50 \quad T = 49 \text{ min}$$

$$\text{Operating time} = (260+55+155)/50 \quad T = 8 \text{ min}$$

For DIA 100 S/F S/s = 200 rpm

$$\text{Feed} = 30 \text{ mm/min}$$

$$T = 43.5/30 = 2 \text{ min}$$

No. of passes = 4

$$\text{Total time} = (574+70+20) \times 4/150 = 17 \text{ min}$$

$$\text{IF } R_{20} = R_{22}, \quad S/s = 600 \text{ rpm}$$

$$F = 150 \text{ mm/min}$$

$$\text{Total time} = (\text{total length} \times \text{no. of passes})/\text{feed} = [((674+250) \times 2)/150] \times 4 = 49 \text{ min}$$

TOTAL OPERATING TIME FOR SETUP-II

$$= 7+1+2+58+3+3+62+49+8+2+17+9+49 \quad T = 270 \text{ min}$$

$$\text{Total operating time for both setup-I \& II} = 270+52 = 322 \text{ min}$$

IV.6. MACHINING TIME FOR HARDEND TOOLS

If the cutting tool is H.S.S/HARDEND cutting speed = 15 m/sec

4.6.1.SETUP-I

For DIA 60 core drill

$$C/s = \pi DN/1000$$

$$N = (1000 \times 15) / (\pi \times 60)$$

$$N = 50 \text{ rpm}$$

$$\text{Feed} = (\text{feed/tooth}) \times \text{no. of teeth} \times \text{rpm} = 0.1 \times 2 \times 50$$

$$F = 10 \text{ mm/min}$$

$$\text{Operating time} = \text{length} / \text{feed} = 92/10 = 10 \text{ min}$$

For DIA 64.5 S/F B. BAR s/s = 50 rpm

$$F = 10 \text{ mm/min}$$

$$\text{Operating time} = \text{length/feed} = 92/10 = 10 \text{ min}$$

For DIA 38 BW DRL

$$C/s = \pi DN/1000 \quad N = (1000 \times 15) / (\pi \times 38) = 120 \text{ rpm}$$

$$\text{Feed} = 0.1 \times 1 \times 120 = 12 \text{ mm/min}$$

$$\text{Operating time} = 30/12 = 3 \text{ min}$$

For DIA 41.5 S/F BAR

$$C/S = \pi DN/1000 \quad N = (1000 \times 15) / (\pi \times 41.5) = 100 \text{ rpm}$$

$$F = 0.1 \times 1 \times 100 = 10 \text{ mm/min}$$

$$\text{Operating time} = \text{length/feed} = 30/10 = 3 \text{ min}$$

For DIA 63 S/MILL

$$\text{Spindle speed} = 120 \text{ rpm}$$

$$\text{Feed} = 50 \text{ mm/min}$$

$$\text{Operating time} = (2\pi R \times \text{no. of passes})/\text{feed} = (2\pi \times 67.5 \times 5)/50 = 42 \text{ min}$$

For DIA 25 END MILL

$$\text{Spindle speed} = 300 \text{ rpm}$$

$$\text{Feed} = 30 \text{ mm/min}$$

$$\text{Operating time} = \text{length/feed} = 480/30 = 16 \text{ min}$$

For DIA 12 END MILL

$$\text{Spindle speed} = 350 \text{ rpm}$$

$$\text{Feed} = 35 \text{ mm/min}$$

Operating time = $532/35 = 16$ min

For DIA 200 S/F BORE

Spindle speed = 30 rpm

Feed = 5 mm/min

Operating time = length/feed = $17/5 = 4$ min

For DIA 42 H₇

Spindle speed = 150 rpm

Feed = 15 mm/min

Operating time = $(87+30)/15 = 8$ min

For DIA 100 S/M

Spindle speed = 100 rpm

Feed = 50 mm/min

Operating time = length/feed = $1850/50 = 37$ min

Total operating time for setup -I

= $10+10+3+3+42+16+5+4+8+37 = 154$ min

IV.6.2 SET UP-II:

For DIA 63 s/m

Spindle speed = 150 rpm

Feed = 50 mm/min

Operating time = length/feed = $1218/50 = 25$ min

For spot

T = $5.5/20 = 1$ min

For oil grooving

Feed = 30 mm/min

Time = length/feed = $[(29+17.5)/30] \times 4 = 8$ min

For 63 S/M F = 50 mm/min

Operating time = (length×no. of passes)/feed = $(558 \times 2 + 162 \times 2)/8/60 = 230$ min

Total length = $2\pi R \times \text{no. of passes} = 2\pi \times 17.5 \times 4$

Time = $(2\pi \times 17.5 \times 4)/80 = 7$ min

No. of passes = 4

Total time = $(570+70+20) \times 4/40 = 67$ min

Spindle speed = 200 rpm

Feed = 50 mm/min

Total time = $[(674+250) \times 2 \times 4]/50 = 147$ min

Total time for setup-II =

$25+1+8+230+7+160+145+22+5+67+147 = 817$ min

Total time for both setups I & II = $148+817 = 965$ min

Total machining time for carbide tools = 322 min

Total machining time for hardened tools = 965 min

By observing the carbide & hardened tools

The machining time for hardened tools is 3 times greater than the carbide tools

IV.7. COST ANALYSIS:

Given

M/c hour rate = Rs.800

For carbide tools total manufacturing cost for 4 pieces = $(322 \times 800 \times 4)/60 = \text{Rs.}17,173$

For Hardened tools total manufacturing cost for 4 pieces = $(965 \times 800 \times 4)/60 = \text{Rs.}51,466$

By using carbide tools, we saved Rs.34,293 for 4 pieces.

IV. CONCLUSION

The 'TOP SLIDE' of horizontal lathe was machined successfully in two set ups on vertical set ups on vertical machining centre (VTC). It has been realised that CNC programming technique is so powerful, that components of intricate profile and tight dimensional tolerance are machined with the sophisticated machine tool like VTC. Machining of such components give way to a compact and revolutionary changes in industrial product. Concept of interchangeability is being felt very much. Thus, maintenance becomes very simple and economical.

It is also seen that numerically controlled machines because of their high initial cost and high machining hour rate are used mainly for highly intricate components requiring high degree of accuracy. It has been observed that the machining time for carbide tools is less as compared to hardened tools.

REFERENCES

- [1]. NC MACHINES- By S.J. MARTIN, peace publishers Moscow 1965
- [2]. NC MACHINES- By YOREM KOREM, industrial press new delhi, 1993
- [3]. MECHATRONICS- By TATA McGraw HILL pvt limited, new delhi
- [4]. CAD/CAM- By ISHRAT M. MIRZANA radiant publishers, 2008